

	Special Process: Hea	at Trea	t System Assessment		
Facility Name: Paulo, St. Louis Di	vision				
Address: 5711 West Park Ave. St. Louis, MO 63110					
Phone Number: (314) 647-7500			Fax Number: (314) 647-7518		
Date of Assessment: 11/9/2022			Date of Previous Assessment: 11/11/2021		
ternal (Captive) Heat Treater (Y/N): N			Commercial Heat Treater (Y/N):	Y	
	Type(s) of Therma	al Proces	sing at this Facility:		
Process Table A			Process Table D		
Carburizing		x	Induction Heat Treating		N/A
Carbonitriding		x	Process Table E		
Carbon Restoration		x	Annealing		x
Neutral Hardening (Quench and Temper)		x	lormalizing		x
Austempering / Martempering		N/A	Stress-Relieving	ress-Relieving	
Tempering		x	Process Table F		
Precipitation Hardening / Aging		x	Low Pressure Processing (Carburizing / Carbonitriding / Neutral Hardening)		N/A
Process Table B			Process Table G	3,	
Nitriding (Gas)		x	Sinter Hardening	er Hardening	
Ferritic-Nitrocarburizing (Gas or Salt)		x	Process Table H		
Process Table C			Ion Nitriding		N/A
Aluminum Heat Treatment		N/A	Process Table I		
			Hot Stamping		N/A
Current Quality Certification(s): IATF 16949:2016, Ford Motor Co. Preferred approved		Supplier,	General Motors High Pressure Die Casting Certified, Gulfstream /		px. 1
Date of Re-assessment (if necessary	/): N/A				
Personnel Contacted:					
lame:	Title:		Phone:	Email:	
Ethan Castle	Key Account Manager		(314) 450-4376	ecastle@paulo.com	
Brian Heitmann	Plant Manager		(314) 450-4381	bheitmann@paulo.com	
uditors/Assessors:	1		1	1	
lame:	Company:		Phone:	Email:	
ulie Evans	Paulo		(314) 450-4399	jevans@paulo.com	
Chad Simpson	Paulo		(314) 450- 4358	csimpson@paulo.com	
lumber of "Not Satisfactory" Find	lings: 0		1	I	
lumber of "Needs Immediate Action	on" Findings: 0				
lumber of "Fail" Findings in the J	ob Audit(s): 0				