

Special Process: Coating System Assessment 2nd Edition			
Facility Name: Paulo Product			
Address: 1307 Rutledge Wa	y, Murfreesboro, Tennessee 3	7129	
Phone Number: 615-896-13	385	Type(s) of Coating Processes	at this Easility:
Fax Number: 615-895-9613		Process Table A	s at this Facility.
Tax Namber: 010 000 0010	,	Pretreatment, Aqueous	
Number of Coating Employe	es at this Facility: 4	Process Table C	
9 1	,	Conversion Coating	
Captive Coater (Y/N): No			
Commercial Coater (Y/N): Y	'es		
Date of Assessment: 8-Octo	ober-2019		
Date of Previous Assessmen	nt: 8-October-2018		
Current Quality Certification(	(s): IATF 16949 (BSI cert. # 78	3120) 9/4/18	
Date of Re-assessment (if n	ecessary): 5/14/19-5/16/19		
Personnel Contacted:			
Name:	Title:	Phone:	Email:
Dave Timken	Plant Manager	615-216-3003	dtimken@paulo.com
Cristian Geist	Plating Manager	615-216-3007	cgeist@paulo.com
Charles Hensley	Quality Manager	615-216-3025	chensleypaulo.com
Auditors/Assessors:			
Name: Cristian Geist	Company: Paulo	Phone: 615-216-3007	Email: cgeist@paulo.com
Charles Hensley	1 , ,	615-216-3025	chensley@paulo.com
-			• •
Number of "Not Satisfactory"	" Findings: 0		
Number of "Needs Immediate	te Action" Findings: 0		
Number of "Cail" Circlings in	the leb Audit(s): 0		
Number of "Fail" Findings in	the Job Audit(s): U		
Number of Process Table Items not meeting Minimum Requirements: 0			
ו אוויייייייייייייייייייייייייייייייייי	Sins not incoming willing in Neq	anomonio. 0	